

Contact Diagram MR 21





Diagram reference

Relay status

Normal

Message



20-1 N/O current



Magnetic system: no current

Magnetic system: excited



20-1 N/C current



Magnetic system: excited

Magnetic system: no current



20-2 N/O current



Magnetic system: no current

Magnetic system: excited



20-2 N/C current



Magnetic system: excited

Magnetic system: no current



20-3 N/O current



Magnetic system: no current

Magnetic system: excited

20-3 N/C current



Magnetic system: excited

Magnetic system: no current

Mechanical indicator flag

 Normal status: black
  Message status: white